

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

#### **FOR OFFICE USE ONLY**

Facility # 2036692 Permit # 02263-2019UPG Request Rec'd 12/02/2019 Amended Date Approval Date 12/2/2019 DS Permit Expires 6/2/2020

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

anny.

Sangha Petroleum, Inc. 12301 S. Archer Ave. Lemont, IL 60439

Contact: Roy Sangha (630) 215-9103

(2) FACILITY - name and address where tanks are located:

Sangha Petroleum, Inc. 12301 South Archer Avenue Lemont, IL 60439

Contact: Roy Sangha (630) 215-9103

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 3) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 3) Piping Shear Valves
- (d) Product to be stored in each tank: (TK#3) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

#### (5) <u>SPECIAL CONTINGENCIES</u>:

Replaced both diesel shear valves

NOTE: Dispenser sumps must be installed if not already existing per 175.410 e) 1)

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Reliable Pump Service and Maintenance 14007 S Bell Road Suite 228 Homer Glen, IL 60491

Contact Person: John Baio, Jr. Phone: (815) 546-7867

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File