

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 7019152 Permit # 02284-2019UPG Request Rec'd 11/26/2019 Amended Date Approval Date 12/5/2019 DS Permit Expires 6/5/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

City of Fairfield

109 North East 2nd Street Fairfield, IL 62837

Contact: Travis Williams (618) 842-9587

(2) FACILITY - name and address where tanks are located:

Fairfield Municipal Airport Highway 45 West Fairfield, IL 62837

Contact: Travis Williams (618) 842-9587

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 4, 5) 10,000
- (b) Type of tanks:
- (c) Type of piping:

(TK # 4, 5) Piping - Fiberglass Single Wall Piping Ameron from pump cabinets back to tanks as a return line.

NOTE: These tanks are BOTH European suction systems. Tank #4 is currently listed in our database as pressurized but the contractor is submitting a notification form to change it.

- (d) Product to be stored in each tank: (TK # 4) Jet A, (TK # 5) Aviation Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 5) Spill Contain Device Single Wall Spill Bucket
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Hinderliter Construction & Maint., Inc. 3601 North St. Joseph Avenue

Contact Person: Mark Hinderliter

Phone: (812) 425-4137

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File