

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 6007982 Permit # 02304-2019UPG Request Rec'd 12/09/2019 Amended Date Approval Date 12/9/2019 DS Permit Expires 6/9/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

HPT TA Properties, LLC 24601 Center Ridge Road Westlake, OH 44145

Contact: Rob Porges (440) 808-7268

(2) FACILITY - name and address where tanks are located:

Travel Centers of America 819 Edwardsville Road I-55 & I-70 & State Route 162 Troy, IL 62294

Contact: Jim Schenker (440) 808-7368

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 8, 9, 10) 20,000, (TK # 11, 12, 13) 12,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 8, 9, 10, 12) Diesel Fuel, (TK # 11) Gasoline Regular, (TK # 13) Gasoline Premium
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 8, 9, 10, 12) Overfill Prev Device Ball Float Vent Valve, (TK # 11, 13) Overfill Prev Device Ball Only Removed Ball Float Vent Valve
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

remove ball float assy from all diesel tanks and confirm 95% shut off on the existing OPV flapper valve

remove the ball only from the Reg and Prem tanks, confirm premium OPV is set to 90%, Reg OPV will require replacment to achieve 90% shut off

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Superior Acquisition LLC d/b/a Superior Equipment Company

Contact Person: Angela Hapgood

7525-A Sussex St. Louis, MO 63143 Phone: (314) 644-6000 Contractor Registration # IL002394 Exp. 2/26/2021

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File