

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

Amended

FOR OFFICE USE ONLY

Facility # 1020246 Permit # 02262-2019UPG Request Rec'd 12/02/2019 Amended Date 12/18/2019 DS Approval Date 12/2/2019 DS Permit Expires 6/2/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Kelley Williamson Company 1132 Harrison Avenue Rockford, IL 61104

Contact: Bob Sanders (815) 397-9410

(2) FACILITY - name and address where tanks are located:

Mt. Morris Mobil 214 E. Witt Street Mount Morris, IL 61054

Contact: Carol Kruger (815) 397-9410

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2) 10,000, (TK # 3) 8,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3) Piping Flexible Double Wall OPW Flexworks, (TK # 1, 2, 3) Piping Ball Valves, (TK # 1, 2, 3) Piping Shear Valves, (TK # 1, 2, 3) Piping Flex Connector Steel, (TK # 1, 2, 3) Piping Single Wall STP/Tanktop Sump, (TK # 1, 2, 3) Piping Single Wall Transition Sump
- (d) Product to be stored in each tank: (TK # 1) Gasoline Regular, (TK # 2) Gasoline Premium, (TK # 3) Gasoline Mid-grade
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 1, 2, 3) Leak Detect - Piping - Stand Alone Sensor Sump Sensor Non-Discriminating in sumps where new DW piping is being installed.

NOTE: Sensors must shut down the submersible pump supplying that line upon detection of a leak per 175.640 a) 1)

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Amendment Reason: Please add disabling ball floats on all tanks. Site will be using overfill alarm for overfill protection. Remove T7 from the permit. Shear valve on 5/6 is low. We will not be able to adjust shear valve height without breaking the pipe below the shear valve. Site has dispenser containment sumps We will be replacing the existing single wall pipe between dispenser 1/2 and the transition sump with Flex

Works double wall pipe. This will be for the regular, midgrade and premium. Site has an existing dispenser containment sump.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Stenstrom Petroleum Services Group

2422 Center Street Rockford, IL 61108 Contact Person: Robert Stenstrom

Phone: (815) 398-6250

Contractor Registration # IL1890 Exp. 4/12/2020

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File