



Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, IL 62703  
2177851020

**FOR OFFICE USE ONLY**

Facility # 2036850  
Permit # 00172-2020UPG  
Request Rec'd 01/31/2020  
Amended Date  
Approval Date 2/3/2020 DS  
Permit Expires 8/4/2020

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

<b>(1) OWNER OF TANKS</b> - Corporation, partnership, or other business entity:  Pilot Travel Centers, LLC 5508 Lonas Rd. Knoxville, TN 37909  Contact: Joey Cupp (865) 588-7488	<b>(2) FACILITY</b> - name and address where tanks are located:  Pilot Travel Center #236 301 Ridge Road Minooka, IL 60447  Contact: Brian Gill (815) 467-4416
--	--

**(3) UPGRADE OR REPAIR OF TANKS:**

- (a) Number and size of tanks being upgraded or repaired: (TK # 4, 5, 6) - 20,000*
- (b) Type of tanks:*
- (c) Type of piping:*
- (d) Product to be stored in each tank: (TK # 4, 5, 6) - Diesel Fuel*
- (e) Type of leak detection being used:*
  - Tank:*
  - Piping:*
- (f) Corrosion Protection being used:*
  - Tank:*
  - Piping:*
- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 4, 5, 6) Spill Contain Device - Double Wall Spill Bucket*
- (h) Overfill prevention devices: (TK # 4, 5, 6) Overfill Prev Device - Overfill Drop Tube Valve*
- (i) Manway accessible at grade:*

- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.

**(5) SPECIAL CONTINGENCIES :**

Installation of three spill containments and three overfill prevention valves on the diesel tanks to comply with State Regulations. Repairs prompted by NOV. We will attempt to remove ball floats- if this does not work they will be disabled.

**NOTE: If ball is simply knocked out, then drop tubes must be set at 90% shut off**

**(6) PERSON, FIRM OR COMPANY PERFORMING WORK:**

Northern Indiana Mechanical, Inc.  
3311 E. 15th Avenue

Contact Person: Mike Kiest  
Phone: (219) 963-1640

Sincerely,



---

Daniel Starks

cc: Storage Tank Safety Specialist  
Division File