

Office of the Illinois State Fire Marshal **Division of Petroleum and Chemical Safety**

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 5020797 Permit # 00774-2020UPG Request Rec'd 05/27/2020 Amended Date Approval Date 5/28/2020 DS Permit Expires 12/1/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

Illinois Ayers Oil Company 6900 Hwy 24 East @ I-172 Quincy, IL 62306

Contact: Curt Adams (217) 434-8662

(2) FACILITY - name and address where tanks are located:

Ayerco Convenience Center #14 430 Stanford Avenue Springfield, IL 62703

Contact: Carl Adams Jr (217) 222-3477

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 5) 15,000, (TK # 6) 8,000, (TK # 7, 8) 6,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 5) Gasoline Regular, (TK # 6) Gasoline Mid-grade, (TK # 7) Gasoline Premium, (TK #8) - Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 5, 6, 7, 8) Overfill Prev Device Overfill Alarm
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Installing Veeder Root TLS overfill alarm and all tanks and removing existing ball float vent valves.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

All Line Equipment, Inc. 5519 Skyline Drive, PO Box 5257 Quincy, IL 62305

Contact Person: Steve Disselhorst Phone: (217) 224-9725

Contractor Registration # IL002319 Exp. 12/23/2021

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File