

Office of the Illinois State Fire Marshal **Division of Petroleum and Chemical Safety**

1035 Stevenson Drive Springfield, IL 62703 2177851020

Amended

FOR OFFICE USE ONLY

Facility # 2016783 Permit # 00916-2020UPG Request Rec'd 06/25/2020 Amended Date 07/13/2020 DS Approval Date 6/29/2020 DS Permit Expires 12/29/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

Prasanthi Nilayum Management, LLC 7408 N. Kedvale Ave. Skokie, IL 60076

Contact: Girish Gheewala (773) 886-2483

(2) FACILITY - name and address where tanks are located:

Pratishtha Corporation - Shell Gas Station & Food Mart 680 North Wolf Road Des Plaines, IL 60610

Contact: Jamish Valsadia (773) 886-2483

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 5, 6) 12,000, (TK # 7) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 5) Piping Other Steel Riser
- (d) Product to be stored in each tank: (TK # 5, 6, 7) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 5, 6, 7) Overfill Prev Device Ball Only Removed Ball Float Vent Valve, (TK # 5, 6, 7) Overfill Prev Device - Overfill Alarm
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) SPECIAL CONTINGENCIES:

Amendment Reason: We removed the ball floats and installed an overfill alarm. We also replaced a spill container, however, the drop tube was seized in the riser, sowe needed to replace the fill riser pipe.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

B & K Equipment Company 2939 175th Street

Contact Person: Ed Angell Phone: (708) 474-3344

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File