

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 4005029 Permit # 01758-2020UPG Request Rec'd 12/11/2020 Amended Date Approval Date 12/14/2020 DS Permit Expires 6/15/2021

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

William A. Leenerman P.O. Box 84 Carlock, IL 61725

Contact: William Leenerman (309) 376-4221

(2) FACILITY - name and address where tanks are located:

Carlock Auto Servicenter 302 W. Washington Carlock, IL 61725

Contact: William Leenerman (309) 376-4221

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 6) 6,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 6) Piping Fiberglass Double Wall A.O. Smith
- (d) Product to be stored in each tank: (TK # 6) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Replacing unrepairable UDC below Diesel fuel island w/ single wall APT LMM 2915 sump. Removing section of existing fuel island to facilitate this replacement. Also replacing approximately 2' product piping and Shear Valve

NOTE: Testing paperwork was recieved that will comply the N.O.V.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Pemco Service Company, Inc. 1040 East Second Street

Contact Person: William "Butch" VonDrehle

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File