

#### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 6017347 Permit # 00515-2021UPG Request Rec'd 04/27/2021 Amended Date Approval Date 4/27/2021 DS Permit Expires 10/27/2021

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) OWNER OF TANKS - Corporation, partnership, or other business

entity:

Jai Ganeshay, Inc. 1257 Lebanon Avenue Belleville, IL 62221

Contact: T J Patel (618) 567-0080

(2) FACILITY - name and address where tanks are located:

BP Food Shop 1257 Lebanon Avenue Belleville, IL 62221

Contact: Manager (618) 567-0080

### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 6) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 6) Piping Fiberglass Single Wall Piping Ameron Dualoy 3000L, (TK # 6) Piping Steel Single Wall Piping, (TK # 6) Piping Other Steel Riser, (TK # 6) Piping Other Submersible Pump, (TK # 6) Piping Ball Valves, (TK # 6) Piping Flex Connector Steel, (TK # 6) Piping Single Wall STP/Tanktop Sump
- (d) Product to be stored in each tank: (TK # 6) Gasoline Regular
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: The existing submerged pump has a bad 4" riser pipe. Remove the existing STP. Install a new STP sump in the same location and modify the existing single wall product piping as needed for the sump installlation. Install different submerged pump, Install new flex connector, ball valve and steel piping to connect the STP.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

UPC Enterprises, LC d/b/a United Petroleum Service 4444 Union Blvd.

Contact Person: Terry Smith Phone: (314) 241-3767

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File