

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 4008717 Permit # 00712-2021UPG Request Rec'd 06/15/2021 Amended Date Approval Date 6/15/2021 DS Permit Expires 12/15/2021

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1)  $\underline{OWNER\ OF\ TANKS}$  - Corporation, partnership, or other business

entity:

Shree Omkara, Inc. 210 E. Vermilion Odell, IL 60460

Contact: Al Patel (815) 998-2413

(2) FACILITY - name and address where tanks are located:

Odell Fast Stop 210 East Vermillion Odell, IL 604600317

Contact: Al Patel (815) 998-2413

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 6,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 1) Leak Detect - Piping - Mechanical Pressurized Line Leak Detection

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

#### (5) <u>SPECIAL CONTINGENCIES</u>:

Removing non functioning electronic line leak detector from diesel (Tank ID 1) and installing Red Jacket FX1DV mechanical leak detector in place of.

Component failed after recent power outages, parts unavailable.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Pemco Service Company, Inc. 1040 East Second Street

Contact Person: William "Butch" VonDrehle

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File