

## Office of the Illinois State Fire Marshal **Division of Petroleum and Chemical Safety**

1035 Stevenson Drive Springfield, IL 62703 2177851020

# **FOR OFFICE USE ONLY**

Facility # 2001729 Permit # 01151-2021UPG Request Rec'd 10/05/2021 Amended Date Approval Date 10/5/2021 DS Permit Expires 4/5/2022

#### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

RDK Ventures, LLC 550 Warrenville Rd., Suite 400

Lisle, IL 60532

Contact: Ralitsa Valkanova (630) 800-6065

(2) FACILITY - name and address where tanks are located:

Circle K #6865 2 North Main Street Algonquin, IL 60102

Contact: Christina Jacobo (331) 251-7343

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1) Piping Other Steel Riser
- (d) Product to be stored in each tank: (TK # 1) Gasoline Regular
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices: (TK # 1) Spill Contain Device Double Wall Spill Bucket
- (h) Overfill prevention devices: (TK # 1) Overfill Prev Device Overfill Drop Tube Valve
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Replace spill container, drop tube and riser on RUL due to drop tube stuck.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Anderson Pump Service, Inc. 19659 South 97th Avenue Mokena, IL 60448

Contact Person: Ronald Anderson Phone: (708) 478-6190

Contractor Registration # IL002275 Exp. 5/21/2022

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File