

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 4006397 Permit # 01323-2021UPG Request Rec'd 11/15/2021 Amended Date Approval Date 11/15/2021 DS Permit Expires 5/17/2022

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Simran Sandhu 140 Hawthrone Road Barrington Hills, IL 61744

Contact: Haji Singh (847) 757-0750

(2) FACILITY - name and address where tanks are located:

Gridley Phillips 66 212 W. Gridley Road Gridley, IL 61744

Contact: Haji (Tony) Singh (847) 757-0750

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 8) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 8) Piping Other Steel Riser
- (d) Product to be stored in each tank: (TK # 8) Gasoline Regular
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Replacing 4" steel pipe riser for ID #8 spill manhole due to manhole failing tank testing and unable to remove drop tube assembly.

Tank will be retested after repair. Necessary spill manhole, overfill prevention and like for like paperwork to be filed after repair.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Total Petroleum Service Company 2421 Washington Road Washington, IL 61571

Contact Person: Greg McCoy Phone: (309) 694-8224 Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File