

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## Amended

#### **FOR OFFICE USE ONLY**

Facility # 2032321 Permit # 01264-2021UPG Request Rec'd 11/02/2021 Amended Date 12/09/2021 DS Approval Date 11/2/2021 DS Permit Expires 5/3/2022

#### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

XPO Logistics Freight, Inc.

2211 Old Earhart Rd., Suite 100 Ann Arbor, MI 48105

Contact: Jeff Sexten (734) 757-1657

(2) <u>FACILITY</u> - name and address where tanks are located:

XPO Logistics Freight, Inc. - XDP 401 W. Touhy Ave. Des Plaines, IL 600182403

Contact: Mike Reidy (847) 930-6270

#### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2) 20,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2) Piping Fiberglass Double Wall Ameron Dualoy 3000/LCX, (TK # 1, 2) Piping Other Submersible Pump, (TK # 1, 2) Piping Single Wall STP/Tanktop Sump
- (d) Product to be stored in each tank: (TK # 1, 2) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 1, 2) Leak Detect - Piping - Mechanical Pressurized Line Leak Detection

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices: (TK # 1, 2) Spill Contain Device Double Wall Spill Bucket
- (h) Overfill prevention devices: (TK # 1, 2) Overfill Prev Device Overfill Drop Tube Valve
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

## (5) <u>SPECIAL CONTINGENCIES</u>:

We are repiping the site with new double wall fiberglass LCX piping along with new dispenser containments and Tank top STP assemblies Replaced piping exceeds 20 feet or 50% of the total pipe run.

Amendment Reason: The layout has been updated as the remote fills were eliminated

NOTES: Dispensers must be a full 10' from all buildings and property lines. If sump sensors are not existing they must be installed and be wired for positive shut down.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

America Petropump Services LLC d/b/a Ampsco Services 4075 Fox Valley Center Dr., Unit 9 Aurora, IL 60504

Contact Person: Ravindra Penmatsa Phone: (312) 286-6722 Contractor Registration # IL002420 Exp. 5/22/2023

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File