

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 6043328 Permit # 00639-2022UPG Request Rec'd 06/14/2022 Amended Date Approval Date 6/14/2022 DS Permit Expires 12/14/2022

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

(2) **FACILITY** - name and address where tanks are located:

BNP Group, Inc. 904 Spyglass Hill Court Caseyville, IL 62232 Countryside Corner 17937 Rt. 177 Nashville, IL 62263

Contact: Bobby Patel (609) 325-1027

Contact: Raj Patel (708) 789-3903

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 2) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 2) Piping Flexible Double Wall A.P.T. Poly Tech P150SC
- (d) Product to be stored in each tank: (TK # 2) Gasoline Premium
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices: (TK # 2) Spill Contain Device Single Wall Spill Bucket
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) **SPECIAL CONTINGENCIES**:

The site failed a tank and product line test. We believe the spill bucket is the cause of the tank test failure. The Prem product line also failed. We will replace the entire Premium product line by removing the existing piping from the existing chase pipe and installing new piping pulled through the existing chase pipe. The existing dispenser and STP sumps will remain and the existing sump sensors and line leak detectors will remain.

Replaced piping exceeds 20 feet or 50% of the total pipe run.

NOTE: A removal permit must be obtained for the piping

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

UPC Enterprises, LC d/b/a United Petroleum Service 4444 Union Blvd. St. Louis, MO 63115 Contact Person: Terry Smith Phone: (314) 241-3767

Contractor Registration # IL002402 Exp. 2/10/2024

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File