



**Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety**
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY

Facility #: 2019445
Permit #: 01043-2023UPG
Request Rec'd: 09/13/2023
Approval Date: 09/13/2023 DS
Permit Expires: 03/13/2024

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for
Petroleum and Hazardous Substances**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: Dept of Veteran Affairs Edward Hines Jr. Hospital 5th & Roosevelt Road, Bldg 218 P.O. Box 5000-138S Hines, IL 60140 Cook County Contact: Martin Jensen 708/202-8387	FACILITY - name and address where tanks are located: Edward Hines Jr. Hospital 5th & Roosevelt Road, Building 218 Hines, IL 60140 Cook County Contact: Sam Librizzi 708/202-8387
---	---

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
25	Diesel Fuel	3,000	Currently in use	Federal
26	Diesel Fuel	40,000	Currently in use	Federal

Tank 25 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Overfill Alarm	Replacing - Overfill Prev Device - Overfill Drop Tube Valve

Tank 26 Equipment

Equipment Type	Permit Equipment	Action
Spill Containment Device	Double Wall Spill Bucket	New

Summary of Work

T25 - Installing overfill alarm. Overfill drop tube listed but not installed

T26 - Install double wall spill bucket

T27 - Removing existing overfill drop tube and installing new.

Special Contingencies

NOTE: Dope tube being replaced under like for like on tank 27

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Stenstrom Petroleum Services Group 2422 Center Street Rockford, IL 61108	Contact Person: Robert Stenstrom Phone: 815/978-9937 Email: johnbu@rstenstrom.com Contractor License # IL1890 Exp. 4/12/2024

Sincerely,

Daniel G. Starks

Daniel Starks