

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov **Amended**

FOR OFFICE USE ONLY

Facility #: 6013612 Permit #: 01106-2023UPG Request Rec'd: 09/26/2023 Amended Date: 10/26/2023 DS Approval Date: 09/26/2023 DS Permit Expires: 03/26/2024

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for **Petroleum and Hazardous Substances**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

Corporation, partnership, or other business entity:

Gateway FS, Inc. P.O. Box 100 Red Bud, IL 62278 Randolph County

Contact: Greg Birchler 618/282-3454

FACILITY

name and address where tanks are located:

Gateway FS 9951 State Rt. 127 Nashville, IL 62263 Washington County

Contact: Brad Maschhoff 618/713-4180

Contractor License # IL002402 Exp. 2/10/2024

Tanks on the Permit For Piping Only

| Tank # | Product | Capacity | Tank Status | Regulated Status |
|--------|--------------------|----------|------------------|------------------|
| 2 | Gasoline - Regular | 10,000 | Currently in use | Federal |
| 5 | B-11 | 10,000 | Currently in use | Federal |

Dispensers on the Permit

| Dispenser | Action |
|-----------|-------------------------|
| 3/4 | Sump / Sensors Changing |

Dispenser 3/4 Equipment

| Equipment Type | Permit Equipment | Action |
|----------------|----------------------|--------|
| Dispenser | Single Wall UDC Sump | New |

Summary of Work

The sear valve under dispenser 3/4 is bad. We will sawcut the existing island form, install new sump, flex connector and shear valve. There is a product line from tank 2 regular in this sump that is not being used, we will install new flex connector and shear valve on this line also.

Special Contingencies

Amendment Reason:

we are working on tank two and tank five- not tank four. same work.

| PERSON, FIRM OR COMPANY PERFORMING WORK: | | | | | |
|--|--|---|--|--|--|
| | 128 Millwell Drive Maryland Heights, MO 63043 | Contact Person: Terry Smith Phone: 314/267-1231 Email: terrys@unitedpetro.com Contractor License # 1,003403 Eye 3/10/3034 | | | |

Sincerely, Daniel J. Starks

Daniel Starks

For Office Use Only

Dispenser 3/4 Equipment

| Equipment Type | Permit Equipment | Action |
|----------------|------------------------|----------|
| Dispenser | Not Installed UDC Sump | Removing |