

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov Amended FOR OFFICE USE ONLY

Facility #: 2024383
Permit #: 01439-2023UPG
Request Rec'd: 12/11/2023
Amended Date:12/14/2023 DS
Approval Date: 12/12/2023 DS
Permit Expires: 06/12/2024

<u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances</u>

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

- Corporation, partnership, or other business entity:

Lehigh Gas Wholesale Services 645 Hamilton, Suite 400 Allentown, PA 18101 (None) County

Contact: Jeremy Holland 610/625-8061

FACILITY

- name and address where tanks are located:

TI 0090

735 E. Belvidere Road Grayslake, IL 60030 Lake County

Contact: Bruce Hill 847/680-5831

Tanks on the Permit For Piping Only

Tank #	Product	Capacity	Tank Status	Regulated Status
2	Gasoline - Regular	12,000	Currently in use	Federal
3	Gasoline - Premium	10,000	Currently in use	Federal

Tank 2 Equipment

Equipment Type	Permit Equipment	Action
Piping Flex Connector Steel		Replacing - Piping - Flex Connector Steel

Tank 3 Equipment

Equipment Type	Permit Equipment	Action
Piping Flex Connector Steel		Replacing - Piping - Flex Connector Steel

Summary of Work

Replace leaking flex connector. Product has been taken out of service.

Also replacing leaking flex under dispenser #1/#2 on the regular.

Special Contingencies

Amendment Reason:

Also need to replace flex connector under #1/#2 - regular

PERSON, FIRM OR COMPANY PERFORMING WORK:				
Stenstrom Petroleum Services Group 2422 Center Street Rockford, IL 61108	Contact Person: Robert Stenstrom Phone: 815/978-9937 Email: johnbu@rstenstrom.com Contractor License # IL1890 Exp. 4/12/2024			

Sincerely, Daniel J. Starks

Daniel Starks