

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY

Facility #: 2045676
Permit #: 01492-2023UPG
Request Rec'd: 12/21/2023
Approval Date:12/22/2023 DS
Permit Expires: 06/24/2024

<u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances</u>

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

- Corporation, partnership, or other business entity:

Kankakee Gas and Wash, LLC 8200 185th Street, Unit K Tinley Park, IL 60487

(None) County

Contact: 708/444-0117

FACILITY

- name and address where tanks are located:

Kankakee Gas and Wash, LLC

174 Court St Kankakee, IL 60901 Kankakee County

Contact: Scott Ensurud 708/805-2525

Tanks on the Permit

| Tank # | Product | Capacity | Tank Status | Regulated Status |
|--------|---------|----------|------------------|------------------|
| 2 | E85 | 10,000 | Currently in use | Federal |

Tank 2 Equipment

| Equipment Type | Permit Equipment | Action | |
|----------------------------|--------------------------|---|--|
| Overfill Prevention Device | Overfill Drop Tube Valve | Replacing - Overfill Prev Device - Overfill Drop Tube Valve | |
| Piping | Other Steel Riser | New | |
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Double Wall Spill Bucket | |

Summary of Work

Replace stuck drop tube and riser for it.

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:

Anderson Pump Service, Inc. 19659 South 97th Avenue

Janiel J. Starke

Mokena, IL 60448

Contact Person: Ron Anderson

Phone: 708/243-9081

Email: steve@andersonpump.com

Contractor License # IL002275 Exp. 5/21/2024

Sincerely,

Daniel Starks