



**Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety**
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY	
Facility #:	7019152
Permit #:	00267-2024UPG
Request Rec'd:	03/07/2024
Approval Date:	03/07/2024 DS
Permit Expires:	09/09/2024

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: City of Fairfield 109 North East 2nd Street Fairfield, IL 62837 Wayne County Contact: Travis Williams 618/842-9587	FACILITY - name and address where tanks are located: Fairfield Municipal Airport Highway 45 West Fairfield, IL 62837 Wayne County Contact: Travis Williams 618/842-9587
--	--

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
4	Jet A	10,000	Currently in use	Federal
5	Aviation Fuel	10,000	Currently in use	Federal

Tank 4 Equipment

Equipment Type	Permit Equipment	Action
Leak Detection - Tank	Automatic Tank Gauging Veeder Root TLS 450 Plus with CSLD	Replacing - Leak Detect - Tank - Automatic Tank Gauging Incon TS 1001

Tank 5 Equipment

Equipment Type	Permit Equipment	Action
Leak Detection - Tank	Automatic Tank Gauging Veeder Root TLS 450 with CSLD	Replacing - Leak Detect - Tank - Automatic Tank Gauging Incon TS 1001

Summary of Work

Faulty ATG unit needs replaced at facility with upgraded TLS 450 ATG device.

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Hinderliter Construction & Maint., Inc. 3601 North St. Joseph Avenue Evansville, IN 47720	Contact Person: Mark Hinderliter Phone: 812/425-4137 Email: compliance@hci4.com Contractor License # IL646 Exp. 4/2/2024

Sincerely,

Daniel G. Starks

Daniel Starks