



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY
Facility #: 2025323
Permit #: 00678-2024ABN
Request Rec'd: 06/03/2024
Approval Date: 06/04/2024 DS
Permit Expires: 12/04/2024

Permit for ABANDONMENT-IN-PLACE of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to abandon- in- place underground storage tank(s) or piping is hereby granted. Such abandonment must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175, and 176. The contractor the permit was issued to shall establish a date certain to perform the UST activity by shall establish a date certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account If the Storage Tank Safety Specialist (STSS) observes evidence of a release, the owner, operator or designated representative of the UST owner/operator must notify the Illinois Emergency Management Agency (IEMA). The incident number shall be given to the STSS prior to his/her leaving the site.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: Village of Bartlett 1150 Bittersweet Dr. Bartlett, IL 60103 Du Page County Contact: Chris Balodimas 630/837-0811	FACILITY - name and address where tanks are located: Village of Bartlett WWTP 1150 Bittersweet Drive Bartlett, IL 60103 Du Page County Contact: Blake Grenlie 630/540-5419
--	---

Tanks on the Permit

Tank #	Capacity	Product	Fill Material	Comments
2	2,500	Diesel Fuel	Inert material mixed with portland cement	

Explanation of Waiver for Abandonment

The UST must be abandoned in place because if removed the electrical service feeding the waste water treatment plant would be undermined. Attached is the laboratory report for the four soil borings completed and samples taken at various depths. Also attached is the site plan showing where the soil borings were placed.

Location of Tanks Being Abandoned

The UST must be abandoned in place because if removed the electrical service feeding the waste water treatment plant would be undermined. Attached is the laboratory report for the four soil borings completed and samples taken at various depths. Also attached is the site plan showing where the soil borings were placed.

Location of Piping Being Abandoned

No piping mentioned in notes nor on site plan

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Orivne, Inc. PO Box 46249 Chicago, IL 606460249	Contact Person: Mike Leyden Phone: 312/656-2009 Email: mleyden@orivne.us Contractor License # IL002408 Exp. 5/1/2025

Sincerely,

Daniel Starks