

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov FOR OFFICE USE ONLY

Facility #: 2047563
Permit #: 00808-2024UPG
Request Rec'd: 07/09/2024
Approval Date:07/09/2024 DS
Permit Expires: 01/09/2025

<u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for</u> <u>Petroleum and Hazardous Substances</u>

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

- Corporation, partnership, or other business entity: Illinois State Tollway Highway Authority 2700 Ogden Avenue Downers Grove, IL 60515 Du Page County

Contact: Manar Nashif 630/241-6800Ext.4841

FACILITY

name and address where tanks are located:
 ISTHA M5 Maintenance Garage

575 W. Central Road Route 90, MP 64.5 (Central Road)

Hoffman Estates, IL 60192

Cook County

Contact: Gery Schauch 847/605-9170

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
2	Gasoline - Regular	10,000	Installed/Not in Use	Federal
3	E85	10,000	Installed/Not in Use	Federal

Tank 2 Equipment

Equipment Type	Permit Equipment	Action
Leak Detection - Piping	Sump Sensor with positive shutdown	New
Leak Decection 1 Iping	in Single Wall STP/Tanktop Sump	, and the state of

Tank 3 Equipment

Equipment Type	Permit Equipment	Action
Leak Detection - Piping	Sump Sensor with positive shutdown in Single Wall STP/Tanktop Sump	New

Summary of Work

Original install permit had European Suction for tanks 2 & 3. However, tanks 2 & 3 DO NOT have european suction, only pressuirzed piping.

We are NOT adding sensors under this permit. The sensors are existing but the permit application insisted I add the sensors with positive shutdown.

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:				
Crowne Industries, Ltd. 651 S. Sutton Road #214 Streamwood, IL 60107	Contact Person: Robert Sumoski Phone: 630/201-4967 Email: yvonne@crownetank.com Contractor License # IL002345 Exp. 5/16/2026			

Sincerely, Carrief J. Starks

Daniel Starks