

## OFFICE OF THE ILLINOIS STATE FIRE MARSHAL Division of Technical Services

1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)524-7605

## FOR OFFICE USE ONLY

Facility # 7-021612
Permit # 00946-2006LIN
Request Rec'd 06/21/2006
Amended Date
Approval Date 7/3/2006 JC
Permit Expires 7/3/2007

## Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

(2) EACH ITY

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

Knapp Oil Co., Inc.  Knapp Mart Citgo  614 S. Commercial	business entity:	(2) FACILITY - name and address where tanks are located:
Xenia, IL 62899  Harrisburg, Saline Co., IL	524 Front Street, P.O. Box 215	614 S. Commercial
Contact: Bill Knapp (618) 678-2211 Contact: Bill Knapp (618) 678-2211	Contact: Bill Knapp (618) 678-2211	Contact: Bill Knapp (618) 678-2211

## (3) INSPECTION OF INTERIOR LINING OF TANKS:

(1) OWNED OF TANKS Committee and the

- (a) Number and size of tanks being inspected: (TK # 1, 2, 3, 4) 8,000 gallons
- (b) Type of tanks: (TK # 1, 2, 3, 4) Existing single wall steel
- (c) Product stored in each tank: (TK # 1, 2, 3) Gasoline, (TK # 4) Diesel Fuel
- (d) Manway accessible at grade:
- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at <a href="www.state.il.us/osfm">www.state.il.us/osfm</a> or by calling (217)785-1020.
- (6) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). Extension request letter received 12/18/06. These tanks were originally lined 09/06/96. They have been using monthly inventory control as a sole method of tank release detection since at least 1986. An alternate method of tank release detection must be implemented by 09/07/06.

(7) PERSON, FIRM OR COMPANY PERFORMING WORK: Bolin Enterprises, Inc.	Contact Person: James Bolin Phone:	
P.O. Box 70,	Contractor Registration #	Exp.
Sincerely,		
cc: Storage Tank Safety Specialist -		

cc: Storage Tank Safety Specialist Fire Department -Office Coordinator -Division File (Rev. - 1/98)