

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov Amended FOR OFFICE USE ONLY

Facility #: 1023707
Permit #: 01466-2024UPG
Request Rec'd: 11/14/2024
Approval Date: 11/14/2024 DS
Amended Date:11/25/2024 DS
Permit Expires: 05/14/2025

<u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for</u> Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

- Corporation, partnership, or other business entity:

Pankaj Patel d/b/a Umiya Maa, LLC 435 West Lena Street Lena, IL 61048

Contact: 630/501-8389

Stephenson County

FACILITY

- name and address where tanks are located:

Lena Food & Liquor 435 W. Lena Street Lena, IL 61048 Stephenson County

Contact: Pankaj Patel 630/501-8389

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
5	Gasoline - Regular	10,000	Currently in use	Federal
6	Gasoline - Premium	10,000	Currently in use	Federal

Tank 5 Equipment

Equipment Type	Permit Equipment	Action
Piping	Other Steel Riser	New
Overfill Prevention Device	Ball Float Vent Valve	Removing

Tank 6 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Ball Float Vent Valve	Removing

Summary of Work

Decommission ball floats, site has overfill valve drop tubes that pass testing. Repermitting to list overfill valves as primary overfill protection for site.

Special Contingencies

Amendment Reason:

Permit was due to broken vapor riser. Upon excavation, discovered a coupler. Able to replace coupler, nipple, and adapter without breaking ground. Spill bucket replacement cancelled.

DEDCON	ETDM (OD COMDA	NNV DEDEAD	MING WORK:

Stenstrom Petroleum Services Group 2422 Center Street

Rockford, IL 61108

Contact Person: Robert Stenstrom

Phone: 815/520-5292

Email: trevorh@rstenstrom.com

Contractor License # IL1890 Exp. 4/12/2026

Sincerely, Carrief J. Starks

Daniel Starks