

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov FOR OFFICE USE ONLY

Facility #: 1023080
Permit #: 01586-2024UPG
Request Rec'd: 12/09/2024
Approval Date:12/09/2024 DS
Permit Expires: 06/10/2025

<u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for</u> <u>Petroleum and Hazardous Substances</u>

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

- Corporation, partnership, or other business entity:

Shree Realty, LLC 1335 May Road Peru, IL 61354 LaSalle County

Contact: Sweety Patel 312/860-5502

FACILITY

- name and address where tanks are located:

Shree Balaji Corp. d/b/a The Junction Mobil

203 La Salle Road Peru, IL 61354 LaSalle County

Contact: Sweety Patel 312/860-5502

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
6	Gasoline - Regular	12,000	Currently in use	Federal
7	Diesel Fuel	12,000	Currently in use	Federal
8	Gasoline - Premium	12,000	Currently in use	Federal

Tank 6 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Ball Float Vent Valve	Removing

Tank 7 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Ball Float Vent Valve	Removing

Tank 8 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Ball Float Vent Valve	Removing

Summary of Work

The ball floats will be removed from all tanks due to testing failures. All tanks have overfill prevention drop tubes set at the correct height.

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:				
2939 175th Street	Contact Person: Ed Angell Phone: 708/474-3344 Email: ed.angell@bkequip.com Contractor License # IL1207 Exp. 2/14/2026			

Sincerely, Carrief J. Starks

Daniel Starks