



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY
Facility #: 4012377
Permit #: 00383-2025UPG
Request Rec'd: 03/31/2025
Approval Date: 03/31/2025 DS
Permit Expires: 09/30/2025

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

| | |
|--|--|
| OWNER OF TANKS - Corporation, partnership, or other business entity: CP Tanks, LLC 811 W. Springfield Ave., Ste 201 Champaign, IL 61820 Champaign County Contact: Rolfe Lann 804/730-1568 | FACILITY - name and address where tanks are located: Village Pantry #1210 SE Corner I-74 & Collision Rd Oakwood, IL 61858 Vermilion County Contact: Dave Marlatt 910/796-2436 |
|--|--|

Tanks on the Permit

| Tank # | Product | Capacity | Tank Status | Regulated Status |
|--------|--------------------|----------|------------------|------------------|
| 8 | Gasoline - Regular | 14,000 | Currently in use | Federal |

Tank 8 Equipment

| Equipment Type | Permit Equipment | Action |
|----------------------------|--------------------------|--------|
| Overfill Prevention Device | Overfill Drop Tube Valve | New |

Summary of Work

Ball Float Overfill Device was Failed and removed, and a new OPW 71-SO Overfill Drop Tube was installed. Work was done with out permit.
We are testing the Overfill to for 95% shut and functionality as well as making sure Ball float was removed.

Special Contingencies

| | |
|---|---|
| PERSON, FIRM OR COMPANY PERFORMING WORK: | |
| Midwest Tank Testing, LLC 2008 Medical Center Dr Monticello, IL 61856 | Contact Person: Stephen T. Hall Phone: 217/714-4305 Email: midwesttanktestingsth@aol.com Contractor License # IL002461 Exp. 1/2/2026 |

Sincerely,

Daniel Starks