



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL
Division of Technical Services
1035 Stevenson Drive
Springfield, Illinois 62703-4259
(217)524-7605

FOR OFFICE USE ONLY
Facility # 5-020796
Permit # 01863-2006LIN
Request Rec'd 12/12/2006
Amended Date
Approval Date 12/14/2006 JC
Permit Expires 6/14/2007

Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

(1) OWNER OF TANKS - Corporation, partnership, or other business entity: Illinois Ayers Oil Company Rt. I-72 & 24, P. O. Box 772, Hwy 24 & 336 Junction Quincy, IL 62301 Contact: Carl Adams Jr (217) 434-8662	(2) FACILITY - name and address where tanks are located: Ayerco Convenience Ctr #12 140 W Main St Mount Sterling, Brown Co., IL Contact: Chris Morrell (217) 773-3146
---	--

(3) INSPECTION OF INTERIOR LINING OF TANKS:

- (a) Number and size of tanks being inspected:* (TK # 2) - 5,000 gallons
- (b) Type of tanks:*
- (c) Product stored in each tank:* (TK # 2) - Gasoline
- (d) Manway accessible at grade:*

- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.**
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.state.il.us/osfm or by calling (217)785-1020.**
- (6) SPECIAL CONTINGENCIES:** Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). Tanks #3 & #4 are past due for the ten year lining inspection. Tanks 2,3,4 were originally lined sometime in 1990 through permit #4166REL. Tank #2 was inspected 11/20/01 through permit #01909-2001LIN. Tanks 2,3,4 had impressed current installed 02/14/90 through permit #3346 UPG/REP. We have no field notes or anything to show if tanks 3 or 4 have ever been inspected since they were originally lined.

(7) PERSON, FIRM OR COMPANY PERFORMING WORK: Bolin Enterprises, Inc. P.O. Box 70,	Contact Person: James Bolin Phone: Contractor Registration # Exp.
--	--

Sincerely,



cc: Storage Tank Safety Specialist -
Fire Department -
Office Coordinator -
Division File
(Rev. - 1/98)