



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY
Facility #: 2016148
Permit #: 01403-2025ABN
Request Rec'd: 10/22/2025
Approval Date: 10/22/2025 DS
Permit Expires: 04/22/2026

Permit for ABANDONMENT-IN-PLACE of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to abandon- in- place underground storage tank(s) or piping is hereby granted. Such abandonment must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175, and 176. The contractor the permit was issued to shall establish a date certain to perform the UST activity by shall establish a date certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account If the Storage Tank Safety Specialist (STSS) observes evidence of a release, the owner, operator or designated representative of the UST owner/operator must notify the Illinois Emergency Management Agency (IEMA). The incident number shall be given to the STSS prior to his/her leaving the site.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: Runa Business Enterprises 14209 Lincoln Avenue Dolton, IL 60419 Cook County Contact: Raja M Yaqub 131/221-75458	FACILITY - name and address where tanks are located: Dolton Gas, Citgo 14209 South Lincoln Dolton, IL 60419 Cook County Contact: Raja M Yaqub 773/284-1855
---	---

Tanks on the Permit

* A combination of inert fill material is not allowed. The listed inert fill material is only allowed to fill the abandoned tank.

Tank #	Capacity	Product	Fill Material *
1	8,000	Gasoline - Regular	Inert material mixed with portland cement

Explanation of Waiver for Abandonment

UST #1 and the previously abandoned UST #2 are located adjacent to each other. UST #2 is positioned partially beneath the canopy and adjacent to the canopy footing; therefore, removal would compromise the structural integrity of the canopy.

Location of Tanks Being Abandoned

UST #1 and the previously abandoned UST #2 are located adjacent to each other. UST #2 is positioned partially beneath the canopy and adjacent to the canopy footing; therefore, removal would compromise the structural integrity of the canopy.

Location of Piping Being Abandoned

Piping being removed under a separate permit.

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:	
RW Collins Company 7225 West 66th Street Chicago, IL 60638	Contact Person: Lisa Kruse Phone: 708/308-8217 Email: admauro@rwcollins.com Contractor License # IL772 Exp. 2/9/2026

Sincerely,

Daniel Starks