

OFFICE OF THE ILLINOIS STATE FIRE MARSHAL Division of Technical Services 1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)524-7605

Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
S & G, Inc. 20049 Pine Grove Court Mokena, IL 60448	S & G, Inc. 15898 S. La Grange Road Orland Park, Cook Co., IL
Contact: Sam LaRocco, SR (708) 479-3776	Contact: Sam KaRocco SR (708) 479-3776

(3) INSPECTION OF INTERIOR LINING OF TANKS:

- (a) Number and size of tanks being inspected: (TK # 2) 6,000 gallons
- (b) Type of tanks: (TK # 2) Existing single wall fiberglass
- (c) Product stored in each tank: (TK # 2) Gasoline
- (d) Manway accessible at grade:
- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at <u>www.state.il.us/osfm</u> or by calling (217)785-1020.
- (6) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). For this permit, the contractor is going to inspect the integrity of the inner portion of the fiberglass tank. This tank, along with tank #4, does not have an existing internal lining (tank #1 & #3 has an existing lining notification form signed by contractor received 07/27/04). Also, it is important that the inspector review the special contingencies of permit #00478-2006REL for a complete review of this site, and for further instructions. Incidentally, this newly approved permit is a replacement for permit #00478-2006REL.

(7) PERSON, FIRM OR COMPANY PERFORMING WORK:

Chicago Tank Lining Inc 600 Hartrey Contact Person: Ray Brand Phone:

Contractor Registration # Exp.

Sincerely,

Jame J affey

cc: Storage Tank Safety Specialist -Fire Department -Office Coordinator -Division File (Rev. - 1/98)