

Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Harper Oil Company 2319 W. Jefferson Springfield, IL 62702	Harper Oil Co #29 Route 4 & 104,RR # 1 Box 175A Auburn, Sangamon Co., IL
Contact: Patrick Ketchum (217) 698-4088	Contact: Fore Roger (217) 438-9900

(3) INSPECTION OF INTERIOR LINING OF TANKS:

- (a) Number and size of tanks being inspected: (TK # 1) 12,000 gallons, (TK # 2, 3, 4) 6,000 gallons, (TK # 5) 10,000 gallons
- (b) Type of tanks: (TK # 1, 2, 3, 4, 5) Existing single wall steel
- (c) Product stored in each tank: (TK # 1, 2, 5) Gasoline, (TK # 3) Diesel Fuel, (TK # 4) Kerosene
- (d) Manway accessible at grade:
- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at <u>www.state.il.us/osfm</u> or by calling (217)785-1020.
- (6) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). According to our records tanks 1,2,3,4 have had a lining since 1986. Tank #5 was lined 06/21/95 through permit #0960-95 REL (tanks 1,2,3,4 were supposed to have been inspected through the same permit; however, the inspector log makes no mention of inspecting tanks 1,2,3,4. He only mentions tank #5 being lined there are no other logs, field notes, notification forms, etc. that can prove tanks 1,2,3,4 were ever inspected we have a few certification audits that "claim" they were inspected when tank #5 was lined, but no other evidence exists). A lining inspection permit application was received 12/27/2000 to inspect tanks 1,2,3,4; however, it was cancelled by the contractor; consequently, it appears tanks 1,2,3,4 may be well over due for an inspection. This situation is similar to permit #00764-2006LIN, and permit #00765-2006LIN.

(7) <u>PERSON, FIRM OR COMPANY PERFORMING WORK</u>:

Superior Equipment Co Inc 3283 Ivanhoe Ave Contact Person: James H Spiros Phone:

Contractor Registration # Exp.

Sincerely,

Janu J Coffey

cc: Storage Tank Safety Specialist -Fire Department -Office Coordinator -Division File (Rev. - 1/98)