



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL  
Division of Technical Services  
1035 Stevenson Drive  
Springfield, Illinois 62703-4259  
(217)524-7605

FOR OFFICE USE ONLY  
Facility # 6-021689  
Permit # 00754-2006FLX  
Request Rec'd 05/23/2006  
Amended Date  
Approval Date 5/24/2006 JC  
Permit Expires 11/24/2006

**Permit for UPGRADE or REPAIR of FLEX CONNECTOR for existing Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair flex connector(s) is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Part 170. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for flex connector of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety. **THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

<b>(1) OWNER OF TANKS</b> - Corporation, partnership, or other business entity:  Martin & Bayley, Inc. 928 County Road 1350 North, P.O. Box 385 Carmi, IL 62821  Contact: Mark Bayley (618) 382-2334	<b>(2) FACILITY</b> - name and address where tanks are located:  Huck's #219 101 E. Broadway Steeleville, Randolph Co., IL  Contact: Mark Bayley (618) 382-2334
--	---

**(3) UPGRADE OR REPAIR OF FLEX CONNECTORS:**

- (a) Number and size of tanks being upgraded or repaired:* (TK # 1, 2) - 10,000 gallons
- (b) Type of flex connector(s):* (TK # 1, 2) - Existing steel flex connectors
- (c) Product stored in each tank:* (TK # 1, 2) - Gasoline
- (d) Corrosion Protection being installed with flex connector(s):* (TK # 1, 2) - (Installing) Flex connector sacrificial spike anode cathodic protection

- (4) The owner must notify this Office when completion of flex connector upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for flex connector to the OSFM prior to the work being performed. Both forms can be obtained at [www.state.il.us/osfm](http://www.state.il.us/osfm) or by calling (217)785-1020.**

- (5) SPECIAL CONTINGENCIES:** Tank #1 was lined from permit #4180 REL on 02/12/90. Tank #2 was lined from permit #4905-92REL on 06/24/92. Permit #02737-2003LIN was to inspect both tanks and permit #02738-2003REL was to reline both tanks; however, there is no evidence in our file to prove an inspection or a relining ever took place from these permits. There are no inspector logs and no contractor signed oaths on notification forms to show any lining work ever took place; consequently, tank #1 is six years past due for a lining inspection and tank #2 is four years past due for a lining inspection.

<b><u>(6) PERSON, FIRM OR COMPANY PERFORMING WORK:</u></b>  Shirley Environmental Testing, Inc.  Nebraska City, NE 68410	Contact Person: Phone:  Contractor Registration #    Exp.
--	--

Sincerely,



cc: Storage Tank Safety Specialist -  
Fire Department -  
Office Coordinator -  
Division File  
(Rev. - 1/98)