

# OFFICE OF THE ILLINOIS STATE FIRE MARSHAL Division of Technical Services

1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)524-7605

## FOR OFFICE USE ONLY

Facility # 2-009878
Permit # 00615-2006LIN
Request Rec'd 05/01/2006
Amended Date
Approval Date 5/2/2006 JC
Permit Expires 11/2/2006

### Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

#### THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

(1) OWNER OF TANKS - Corporation, partnership, or other business entity:

Nilkanth Varni, Inc.

139 W. Washington
West Chicago, IL 60185

Contact: Turin Patel (630) 293-5853

(2) FACILITY - name and address where tanks are located:

West Chicago Marathon
139 W. Washington Street
West Chicago, Du Page Co., IL

Contact: Turin Patel (630) 293-5853

## (3) INSPECTION OF INTERIOR LINING OF TANKS:

(a) Number and size of tanks being inspected: (TK # 1, 2) - 10,000 gallons

(b) Type of tanks: (TK # 1, 2) - Existing single wall STI P3

(c) Product stored in each tank: (TK # 1, 2) - Gasoline

(d) Manway accessible at grade:

- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at <a href="www.state.il.us/osfm">www.state.il.us/osfm</a> or by calling (217)785-1020.
- (6) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). For further information on this site refer to contingencies from revised permit #00541-2006CAT. Original notification forms for these tanks (05/02/86, 11/18/87, and 06/27/89) state the tanks are lined. There is no evidence in file to show an inspection has ever occurred. This permit was attained as a result of a notice of violation #E00000020060460.

#### (7) PERSON, FIRM OR COMPANY PERFORMING WORK:

Armor Shield Of Wisconsin 4623 Hillcrest Parkway Contact Person: George Bennett

Phone:

James J Coffey

Contractor Registration # Exp.

Sincerely.

cc: Storage Tank Safety Specialist -Fire Department -

Office Coordinator - Division File

(Rev. - 1/98)