



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL
Division of Technical Services
 1035 Stevenson Drive
 Springfield, Illinois 62703-4259
 (217)524-7605

FOR OFFICE USE ONLY
Facility # 2-007398
Permit # 00371-2006REM
Request Rec'd 03/14/2006
Amended Date
Approval Date 3/15/2006 JC
Permit Expires 9/15/2006

Permit for REMOVAL of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to remove underground storage tank(s) or piping is hereby granted. Such removal shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled. **THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

<p>(1) OWNER OF TANKS - Corporation, partnership, or other business entity: Community High School District 218 10701 S Kilpatrick Ave Oak Lawn, IL 60453 Contact: Hickey John (708) 424-2000 Ext. 505</p>	<p>(2) FACILITY - name and address where tanks are located: Alan B Shepard High School 13049 S Ridgeland Ave Palos Heights, Cook Co., IL Contact: R. Lee Scheidel (312) 597-6300 Ext. 135</p>
--	--

(3) REMOVAL OF TANKS:

- (a) *Number and size of tanks being removed:* (TK # 1) - 20,000 gallons
- (b) *Product stored in each tank:* (TK # 1) - Diesel Fuel
- (c) *Reason of tanks being removed:*
- (d) *If tank(s) is leaking, indicate IEMA incident number:*
- (e) *Date each tank was last used:* (TK # 1) - 01/01/1989

(4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.state.il.us/osfm or by calling (217)785-1020.

(5) SPECIAL CONTINGENCIES: Tank #1 was had a permit application in Oct. of 1994 to abandon this tank but it was denied. A notification form later in the file claims that it was abandoned; however, we have no permit log to prove this. STSS must thoroughly field verify "existing" equipment for tank #3 (the information in file is vague and contradictory as to exactly what is "existing"). The "existing" is gathered through recent certification audits that contradict past information. The main item to check is the tank leak detection method. Is the tank really double wall, and is it using interstitial monitoring for the tank leak detection method?

<p>(6) PERSON, FIRM OR COMPANY PERFORMING WORK: 19140 104Th Avenue</p>	<p>Contact Person: Phone: Contractor Registration # Exp.</p>
---	--

Sincerely,

cc: Storage Tank Safety Specialist -
 Fire Department -
 Office Coordinator -
 Division File
 (Rev. - 1/98)