



**OFFICE OF THE ILLINOIS STATE FIRE MARSHAL**  
**Division of Technical Services**  
 1035 Stevenson Drive  
 Springfield, Illinois 62703-4259  
 (217)524-7605

<b>FOR OFFICE USE ONLY</b>
Facility # 7-020850
Permit # 00136-2006LIN
Request Rec'd 01/11/2006
Amended Date
Approval Date 1/19/2006 JC
Permit Expires 7/19/2006

**Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.**

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

**THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

<p><b>(1) OWNER OF TANKS</b> - Corporation, partnership, or other business entity:</p> <p>Russell Oil Company          P.O. Box 73, Highway 34          Galatia, IL 62935</p> <p>Contact: Leon Russell (618) 268-4722</p>	<p><b>(2) FACILITY</b> - name and address where tanks are located:</p> <p>Russell Oil Co          Hwy 45          Carrier Mills, Saline Co., IL</p> <p>Contact: Terry Stevens (618) 268-4722</p>
---	--

**(3) INSPECTION OF INTERIOR LINING OF TANKS:**

- (a) *Number and size of tanks being inspected:* (TK # 5) - 4,000 gallons, (TK # 6) - 1,000 gallons
- (b) *Type of tanks:* (TK # 5, 6) - Existing single wall steel
- (c) *Product stored in each tank:* (TK # 5) - Gasoline, (TK # 6) - Diesel Fuel
- (d) *Manway accessible at grade:*

- (4) **Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.**
- (5) **The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at [www.state.il.us/osfm](http://www.state.il.us/osfm) or by calling (217)785-1020.**
- (6) **SPECIAL CONTINGENCIES:** Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). Tanks #5 & #6 were lined 04/26/96 from permit #0533-96REL. STSS should field verify whether or not tank #6 has a ball float vent valve for overfill prevention (the system is European suction). Permit #1051-96UPG was to install single wall fiberglass piping, an automatic tank gauge, line leak detectors, manholes, and ball float valves for all tanks; however, there is no log or notification form to verify if this was done - all "existing" equipment is coming from various certification audits.

<b>(7) PERSON, FIRM OR COMPANY PERFORMING WORK:</b>	
<p>Tank Tech          PO Box 17</p>	<p>Contact Person: David Russell          Phone:            Contractor Registration #    Exp.</p>

Sincerely,

*James J. Coffey*

cc: Storage Tank Safety Specialist -  
 Fire Department -  
 Office Coordinator -  
 Division File  
 (Rev. - 1/98)