

Permit for UPGRADE or REPAIR of FLEX CONNECTOR for existing Underground Storage Tank(s) and Piping for Petroleum and Hazardous

Substances.

Permission to upgrade or repair flex connector(s) is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Part 170. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for flex connector of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety. **THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE**.

 <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity: 	(2) <u>FACILITY</u> - name and address where tanks are located:
Speedway SuperAmerica, LLC P.O. Box 1500 Springfield, OH 45501-1500	Speedway #7559 1501 State St Lawrenceville, Lawrence Co., IL
Contact: Danny Coffey (937) 863-7072	Contact: Jeffrey A Carter (618) 943-6373

(3) UPGRADE OR REPAIR OF FLEX CONNECTORS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 3) 10,000 gallons
- (b) Type of flex connector(s): (TK # 3) (Installing) Steel flex connectors
- (c) Product stored in each tank: (TK # 3) Gasoline
- (d) Corrosion Protection being installed with flex connector(s): (TK # 3) Existing sacrificial spike anode cathodic protection on flex connectors
- (4) The owner must notify this Office when completion of flex connector upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for flex connector to the OSFM prior to the work being performed. Both forms can be obtained at <u>www.state.il.us/osfm</u> or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: STSS must field verify whether or not these systems each have an automatic tank gauge. Certification audits show both SIR and an automatic tank gauge being used. Tanks 1 & 2 were lined 06/03/98 from permit #0793-98REL. The log for the reline permit states tank #3 is a stip 3 tank, and was not lined. This flex connector permit is for tank #3 (premium) as indicated from the application.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Petro Maintenance

Robinson, IL 62454

Contact Person: Phone:

Contractor Registration # Exp.

Sincerely,

Janu & Coffey

cc: Storage Tank Safety Specialist -Fire Department -Office Coordinator -Division File (Rev. - 1/98)