



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, Illinois 62703-4259  
(217)785-1020

**Permit for Emergency Repair Request on  
09/06/2013**

**FOR OFFICE USE ONLY**

Facility # 2-012722  
Permit # 00921-2013UPG  
Request Rec'd 09/12/2013  
Amended Date  
Approval Date 9/12/2013 JC  
Permit Expires 9/26/2013

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

<b>(1) OWNER OF TANKS</b> - Corporation, partnership, or other business entity:  PAV2, LLC 24501 Ecorse Road Taylor, MI 48180  Contact: Mike Evans (313) 220-2463	<b>(2) FACILITY</b> - name and address where tanks are located:  Citgo - Franklin Park 2805 N. Mannheim Rd. Franklin Park, Cook Co., IL  Contact: Sandy (313) 662-3618
---	--

**(3) UPGRADE OR REPAIR OF TANKS:**

- (a) *Number and size of tanks being upgraded or repaired:* (TK # 3, 4, 5) - 10,000 gallons
- (b) *Type of tanks:*
- (c) *Type of piping:* (TK # 3, 4, 5) - (Installing) partial Fiberglass Single Wall Piping Ameron to repair short sections of product piping (approximately 2' for each damaged section of piping) relative to tanks 3,4,5 due to soil boring damage located near dispenser #7/8, and two short sections of vent piping for tanks 4 & 5 just outside of the tank field in proximity to tank #5 (see site plan for details / location).
- (d) *Product to be stored in each tank:* (TK # 3) - Gasoline, (TK # 4, 5) - Diesel Fuel
- (e) *Type of leak detection being used:*
  - Tank:*
  - Piping:*
- (f) *Corrosion Protection being used:*
  - Tank:*
  - Piping:* (TK # 3, 4, 5) - (Installing) partial Fiberglass Non-Corrosive
- (g) *Spill containment devices, piping, and dispenser containment devices:*
- (h) *Overfill prevention devices:*
- (i) *Manway accessible at grade:*

- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.

- (5) **SPECIAL CONTINGENCIES:** Emergency repair request was received 09/06/13. All emergency repairs require a permit applied for after the fact on the next business day and require a final inspection scheduled pursuant to section 175.320(d)(4) 10 days after issuance of the permit (see section 175.710(a)). Final inspection must be scheduled by 09/26/13.

<b><u>(6) PERSON, FIRM OR COMPANY PERFORMING WORK:</u></b>  Anderson Pump Service, Inc. 19659 South 97th Avenue Mokena, IL 60448	Contact Person: Chris Derro Phone: (708) 243-9081  Contractor Registration # IL-002275 Exp. 05/21/2014
--	---

Sincerely,

Jim Coffey

cc: Storage Tank Safety Specialist -  
Fire Department -  
Division File  
(Rev. - 9/10)