

OFFICE OF THE ILLINOIS STATE FIRE MARSHAL Division of Technical Services

1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)524-7605

FOR OFFICE USE ONLY

Facility # 2-024313
Permit # 00284-2010LIN
Request Rec'd 03/17/2010
Amended Date
Approval Date 3/17/2010 JC
Permit Expires 9/17/2010

Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

(2) EACH ITV

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Charter National Bank & Trust 2200 W. Higgins Rd. Hoffman Estates, IL 60169	Higgins Marathon 1300 W. Higgins Road Hoffman Estates, Cook Co., IL
Contact:	Contact: Anthony Kurian (847) 293-4803

(3) INSPECTION OF INTERIOR LINING OF TANKS:

- (a) Number and size of tanks being inspected: (TK # 1, 2) 8,000 gallons, (TK # 3, 4) 6,000 gallons
- (b) Type of tanks:

(1) OWNED OF TANKS Comm

- (c) Product stored in each tank: (TK # 1, 2, 3) Gasoline, (TK # 4) Diesel Fuel
- (d) Manway accessible at grade: Contractor states there are existing manways.
- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.state.il.us/osfm or by calling (217)785-1020.
- (6) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). Contractor states there are existing manways.

(7) PERSON, FIRM OR COMPANY PERFORMING WORK:

Armor Shield Of Wisconsin 4623 Hillcrest Parkway Slinger, WI 53086 Contact Person: George Bennett

Phone:

James J Coffey

Contractor Registration # Exp.

Sincerely,

cc: Storage Tank Safety Specialist -

Fire Department - Office Coordinator -

Division File (Rev. - 1/98)