



Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, IL 62703  
(217)785-1020

**FOR OFFICE USE ONLY**

Facility # 2010113  
Permit # 00395-2015LIN  
Request Rec'd 05/08/2015  
Amended Date  
Approval Date 5/8/2015 SB  
Permit Expires 11/10/2015

**Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.**

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Parts 174, 175 and 176. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, at which time the UST activity shall be scheduled. **THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

(1) **OWNER OF TANKS** - Corporation, partnership, or other business entity:

Founders Bank Trust #5-1196  
9742 Roberts Road  
Palos Hills, IL 60465

Contact: Bassam R Shehayber (708) 430-1711

(2) **FACILITY** - name and address where tanks are located:

Midlothian Gas  
14453 South Pulaski Road  
Midlothian, IL 60445

Contact: Samir Shehayber (708) 945-0946

(3) **INSPECTION OF INTERIOR LINING OF TANKS:**

(a) *Number and size of tanks being inspected: (TK # 1) - 6,000*

(b) *Type of tank(s):*

(c) *Product stored in each tank: (TK # 1) - Gasoline*

(d) *Manway accessible at grade: (TK # 1) Existing*

(4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.

(5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) by calling (217)785-1020.

(6) **SPECIAL CONTINGENCIES** : Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by section 175.500.

(6) **PERSON, FIRM OR COMPANY PERFORMING WORK:**

Bolin Enterprises, Inc.  
506 North East 15th Street PO Box 70  
Casey, IL 62420

Contact Person: Scott Justice  
Phone: (217) 932-4533  
Contractor Registration # IL002333 Exp. 10/10/2016

Sincerely,

Shelly Bradley

cc: Storage Tank Safety Specialist  
Division File