

### Office of the Illinois State Fire Marshal **Division of Petroleum and Chemical Safety**

1035 Stevenson Drive Springfield, IL 62703 2177851020

# **FOR OFFICE USE ONLY**

Facility # 2011567 Permit # 00786-2015LIN Request Rec'd 08/10/2015 Amended Date Approval Date 8/11/2015 DS Permit Expires 2/11/2016

# Permit for INS PECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Parts 174, 175 and 176. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, at which time the UST activity shall be scheduled. THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

OM Richton Park Oil, Inc. 3600 Sauk Trail Richton Park, IL 60471

Contact: Kalpesh Patel (630) 229-4953

(2) FACILITY - name and address where tanks are located:

OM Richton Park Oil, Inc. 3600 Sauk Trail Richton Park, IL 60471

Contact: Patel Kapesh (630) 229-4953

### (3) INSPECTION OF INTERIOR LINING OF TANKS:

- (a) Number and size of tanks being inspected: (TK # 4) 4,000
- (b) Type of tank(s):
- (c) Product stored in each tank: (TK # 4) Diesel Fuel
- (d) Manway accessible at grade: (TK # 4) Existing
- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.sfm.illinois.govor by calling (217)785-1020.
- (6) <u>SPECIAL CONTINGENCIES</u>: Tank relining lining inspection and entry permit work in reference to manways/manholes must abide by section 175.500.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Armor Shield of Wisconsin 4623 Hillcrest Parkway Slinger, WI 53086

Contact Person: George Bennett Phone: (262) 644-6447

Contractor Registration # IL1707 Exp. 4/18/2016

Sincerely,

Daniel Starks

Janiel J. Starke

cc: Storage Tank Safety Specialist Division File