



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
2177851020

Extended/Amended

FOR OFFICE USE ONLY

Facility # 2014378
Permit # 01147-2018UPG
Request Rec'd 08/18/2018
Amended Date 09/19/2018 Met
Approval Date 8/21/2018 DS
Permit Expires 8/21/2019

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity: US Dept of Military Affairs 3001 N Green Bay Rd North Chicago, IL 60064 Contact: Shawn Taylor (847) 578-3722	(2) <u>FACILITY</u> - name and address where tanks are located: VA Medical Center 3001 N Green Bay Rd North Chicago, IL 60064 Contact: Shawn Taylor (847) 578-3722
--	--

(3) UPGRADE OR REPAIR OF TANKS:

(a) *Number and size of tanks being upgraded or repaired: (TK # 8) - 5,000, (TK # 9, 12) - 2,000, (TK # 13) - 1,000, (TK # 14) - 2,500, (TK # 15) - 3,000, (TK # 16) - 10,000*

(b) *Type of tanks:*

(c) *Type of piping:*

(d) *Product to be stored in each tank: (TK # 8, 12, 13, 14, 15, 16) - Diesel Fuel, (TK # 9) - Gasoline*

(e) *Type of leak detection being used:*

Tank: (TK # 8, 9, 12, 13, 14, 15, 16) Leak Detect - Tank - Automatic Tank Gauging Veeder Root TLS 300c, (TK # 8, 9, 12, 13, 14, 15, 16) Leak Detect - Tank - Interstitial Monitoring Veeder Root TLS 300c

Piping: (TK # 8, 9, 12, 13, 14, 15) Leak Detect - Piping - Piping Sump Sensors Interstitial Monitoring Veeder Root TLS 300c

(f) *Corrosion Protection being used:*

Tank:

Piping:

(g) *Spill containment devices, piping, and dispenser containmnt devices:*

(h) *Overfill prevention devices:*

(i) *Manway accessible at grade:*

(4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) SPECIAL CONTINGENCIES :

There was no existing sump sensor in the sleeve around the exisiting manway on tank #16

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:


Metro Environmental Contractors, Inc. dba Metro Tank & Pump Company

Contact Person: Warren Cherner
Phone: (847) 465-4000

1111 West Dundee Road
Wheeling, IL 600903936

Contractor Registration # IL102 Exp. 2/7/2020

Sincerely,

A handwritten signature in cursive script, reading "Daniel H. Starks", is written over a horizontal line.

Daniel Starks

cc: Storage Tank Safety Specialist
Division File