

### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

### **FOR OFFICE USE ONLY**

Facility # 2043301 Permit # 01111-2019UPG Request Rec'd 06/10/2019 Amended Date Approval Date 6/10/2019 DS Permit Expires 12/10/2019

### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

. Ni. 41. Character II. C

Zion Ninth Street, LLC 6111 Broken Sound Parkway NW, Ste. 110

Boca Raton, FL 33484

Contact: Ilya Sason (561) 988-1982

(2) <u>FACILITY</u> - name and address where tanks are located:

FedEx Freight, Inc.-ZON 5600 9th Street Zion, IL 60099

Contact: Eric Foss (847) 731-1930

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 20,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1) Piping Fiberglass Double Wall NOV Fiberglass Systems Red Thread IIA fiberglass piping, (TK # 1) Piping Shear Valves
- (d) Product to be stored in each tank: (TK # 1) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 1) Leak Detect - Piping - Non-Discriminating Sump Sensor Interstitial Monitoring Veeder Root

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Remove 4 under dispenser containment sumps and replace with new Bravo fiberglass Model #B1670-S30. Install new Veeder-Root sump sensors in all 4 sumps. Install new Gasboy Atlas Master/Satellite configured dispensers. Remove and replace the Diesel submersible motor.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Crowne Industries, Ltd. 651 S. Sutton Road #214

Contact Person: Robert Sumoski Phone: (630) 497-9009 Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File