

OFFICE OF THE ILLINOIS STATE FIRE MARSHAL Division of Technical Services

1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)524-7605

FOR OFFICE USE ONLY

Facility # 4-008078
Permit # 00117-2008LIN
Request Rec'd 01/22/2008
Amended Date
Approval Date 1/22/2008
JC
Permit Expires 7/22/2008

Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
SNC JJ Effingham VI, LLC P.O. Box 250, Effingham, IL 62401	Jumpin Jimmy's 15956 N. US Hwy 45 Effingham, Effingham Co., IL
Contact: Kathy Wines	Contact: Kathy Wines

(3) <u>INSPECTION OF INTERIOR LINING OF TANKS:</u>

- (a) Number and size of tanks being inspected: (TK # 1, 3) 8,000 gallons, (TK # 2) 12,000 gallons, (TK # 4) 6,000 gallons
- (b) Type of tanks:
- (c) Product stored in each tank: (TK # 1, 2, 3) Gasoline, (TK # 4) Diesel Fuel
- (d) Manway accessible at grade: Contractor states there are no blted manways at grade, and none will be installed.
- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.state.il.us/osfm or by calling (217)785-1020.

James of Coffey

(6) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10).

(7) PERSON, FIRM OR COMPANY PERFORMING WORK:

Bolin Enterprises, Inc. P.O. Box 70, Casey, IL 62420 Contact Person: Scott Justice Phone: (217) 932-4533

Contractor Registration # Exp.

Sincerely,

cc: Storage Tank Safety Specialist -

Fire Department -Office Coordinator -Division File

(Rev. - 1/98)