

#### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

### **FOR OFFICE USE ONLY**

Facility # 2024151 Permit # 02390-2019UPG Request Rec'd 12/24/2019 Amended Date Approval Date 12/30/2019 DS Permit Expires 6/30/2020

#### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Shree GI Krupa II Real Estate, LLC 221 Hawk Hollow Drive

Bartlett, IL 60103

Contact: ARUN PATEL (630) 529-0262

(2) FACILITY - name and address where tanks are located:

BP

136 South Gary Avenue Bloomingdale, IL 60108

Contact: Rajendra Patel (708) 990-5721

#### (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 4) 15,000, (TK # 5, 6) 10,000, (TK # 7) 6,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 4, 5, 6, 7) Piping Fiberglass Double Wall Ameron Dualoy 3000/LCX from existing tanks to existing dispenser locations as shown in site plan, (TK # 4, 5, 6, 7) Piping Other Steel Riser, (TK # 4, 5, 6, 7) Piping Positive Shutoff Valves, (TK # 4, 5, 6, 7) Piping Shear Valves, (TK # 4, 5, 6, 7) Piping Flex Connector Steel
- (d) Product to be stored in each tank: (TK # 4, 5) Gasoline Regular, (TK # 6) Gasoline Premium, (TK # 7) Ultra Low Sulfur Diesel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 4, 5, 6, 7) Spill Contain Device Double Wall Spill Bucket
- (h) Overfill prevention devices: (TK # 4, 5, 6, 7) Overfill Prev Device Overfill Drop Tube Valve
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

## (5) <u>SPECIAL CONTINGENCIES</u>:

we are installing new double wall piping new dispenser bravo sumps, new spill buckets double wall, new raiser for all the tanks we are removing the ball floats

**NOTE:** Site has existing sump sensors

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

America Petropump Services LLC d/b/a Ampsco Services 4075 Fox Valley Center Dr., Unit 9
Aurora, IL 60504

Contact Person: Kiran Patibandla Phone: (630) 649-8699 Contractor Registration # IL002420 Exp. 5/22/2021

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File