



Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, IL 62703  
2177851020

**FOR OFFICE USE ONLY**

Facility # 3047048  
Permit # 00652-2020REM  
Request Rec'd 04/30/2020  
Amended Date  
Approval Date 5/4/2020 DS  
Permit Expires 11/5/2020

**Permit for REMOVAL of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to remove underground storage tank(s) or piping is hereby granted. Such removal shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, at which time the UST activity shall be scheduled. **THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

<p>(1) <b><u>OWNER OF TANKS</u></b> - Corporation, partnership, or other business entity:</p> <p>Ameren Illinois 305 E Calhoun Macomb, IL 61455</p> <p>Contact: Brian Holderness (314) 620-1367</p>	<p>(2) <b><u>FACILITY</u></b> - name and address where tanks are located:</p> <p>Ameren Illinois 305 E Calhoun Macomb, IL 61455</p> <p>Contact: Brian Holderness (314) 620-1367</p>
---	---

(3) **REMOVAL OF TANKS:**

- (a) *Number and size of tanks being removed: (TK # 1, 2) - 2,000*
- (b) *Description/location of piping being removed:*
- (c) *Product to be stored in each tank: (TK # 1, 2) - Heating Oil*
- (d) *Reason of tanks being removed:*
- (e) *If tank(s) is leaking, indicate IEMA incident number:*
- (f) *Date each tank was last used: (TK # 1, 2) - 12/31/1973*

- (4) The owner must notify this Office when completion of tank removal has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020. After removal is completed, the owner/operator shall perform a site assessment by measuring for the presence of a release where contamination is most likely to be present at the UST site. This is in accordance with the Illinois Administrative Code 176.360 (a) regulations and 40 CFR Part 280.72 (a) Federal Register Requirement.

(5) **SPECIAL CONTINGENCIES :**

Both tanks were accidentally discovered by another contractor performing a remedial action at the former manufactured gas plant. One tank (Tank 2) is already uncovered and has been moved. The other (Tank 1) is partially uncovered with a sizeable hole torn into the top of it. Bodine has been contracted to remove both tanks per State of Illinois regulations.

Bodine collected a liquid sample from Tank 1. Analysis should be available by close of business today Monday, May 5th. Piping perforations are not visible in either tank. Bodine intends to cut holes in Tank 2 to determine liquid volume and liquid characteristics. Perforations are also necessary to access and remove liquid contents. Tank 1 contains an estimated 1,600 gallons of liquid and sludge. Tank 2 contents are unknown.

Tank removal is planned over a 3-day period. Day 1 involves removing the liquids from both tanks and reducing explosive vapors as necessary. Day 2 involves removing any additional liquids, cleaning the top of Tank 1, and determining a method to attach chains. Day 3 will have the OSFM present to approve and witness the tank pull. Both tanks will be removed from the excavation, cleaned, and removed from the site on Day 3.


Tank 1 not visible in the photo. Tank 2 is sitting at an angle.

(6) **PERSON, FIRM OR COMPANY PERFORMING WORK:**

Bodine Environmental Service, Inc.  
5350 East Firehouse Road  
Decatur, IL 62521

Contact Person: Bob Bryson  
Phone: (217) 428-4381  
Contractor Registration # IL1124 Exp. 5/30/2020

Sincerely,

---

Daniel Starks

**cc:** Storage Tank Safety Specialist  
Division File