

#### Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 2025492 Permit # 00764-2020LIN Request Rec'd 05/26/2020 Amended Date Approval Date 5/26/2020 DS Permit Expires 11/28/2020

## Permit for INS PECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Parts 174, 175 and 176. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, at which time the UST activity shall be scheduled. **THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.** 

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Kapil Singh, LLC 6347 W. Roosevelt Rd. Berwyn, IL 60402

Contact: Kapil Singh (630) 205-6429

(2) FACILITY - name and address where tanks are located:

Kapil Singh, LLC d/b/a Berwyn Fuel Stop 6347 W. Roosevelt Rd. Berwyn, IL 60402

Contact: Kapil Singh (630) 205-6429

### (3) <u>INSPECTION OF INTERIOR LINING OF TANKS:</u>

- (a) Number and size of tanks being inspected: (TK # 1, 2) 10,000, (TK # 3) 4,000
- (b) Type of tank(s):
- (c) Product stored in each tank: (TK # 1) Gasoline Regular, (TK # 2) Gasoline Premium, (TK # 3) Diesel Fuel
- (d) Manway accessible at grade: (TK # 1) Existing, (TK # 2) Existing, (TK # 3) Existing
- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing upgrading or interior lining is authorized with this permit.
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.sfm.illinois.govor by calling (217)785-1020.
- (6) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by section 175.500. Purge, clean and inspect the internal lining of the following tanks in accordance with NLPA-631 and State of Illinois 175 regulations:

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Armor Shield of Wisconsin 1875 Highland Court Slinger, WI 53086 Contact Person: Clayton Bennett Phone: (262) 644-6447

Contractor Registration # IL1707 Exp. 4/18/2022

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File