

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2020664 Permit # 01014-2020UPG Request Rec'd 07/20/2020 Amended Date Approval Date 7/20/2020 DS Permit Expires 1/20/2021

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

relake Mobil

Grayslake Mobil, Inc. 33199 N. US Highway 45 Grayslake, IL 60030

Contact: Litty John (847) 312-7151

(2) FACILITY - name and address where tanks are located:

Grayslake Mobil 33191 North US Highway 45 Grayslake, IL 60030

Contact: Juve Castrejon (847) 312-7151

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 7, 8) 10,000, (TK # 9) 6,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 7) Piping Other Steel Riser
- (d) Product to be stored in each tank: (TK # 7, 8) Gasoline Regular, (TK # 9) Gasoline Premium
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 7, 8, 9) Spill Contain Device Single Wall Spill Bucket
- (h) Overfill prevention devices: (TK # 7, 8, 9) Overfill Prev Device Overfill Drop Tube Valve
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Replacing drop tube and spill container on all 3 tanks. Replacing riser for spill container and stick port on tanks 7.

Tank 8

NOTE: No existing ball floats

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Contact Person: Ron Anderson

Anderson Pump Service, Inc. 19659 South 97th Avenue Mokena, IL 60448 Phone: (708) 478-6190 Contractor Registration # IL002275 Exp. 5/21/2022

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File