

Permit for ENTRY into Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to enter underground storage tank(s) is hereby granted. Such tank entry shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled. THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

| (1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity: | (2) <u>FACILITY</u> - name and address where tanks are located: |
|---|---|
| Exxon Mobil Oil Corporation | Mobil 13248 |
| 7300 W. Friendly Avenue, P.O. Box 22087, CMS Mailstop F-76 | 294 E. Rt. 60 |
| | Vernon Hills, Lake Co., IL |
| Greensboro, NC 27420-2087 | Contact: Costa Jor 7083678997 (847) 367-8997 |
| Contact: Eric McPhee (800) 253-8054 | Contact. Costa Joi 7083078997 (847) 507-8997 |

(3) ENTRY OF TANKS:

- (a) Number and size of tanks being entered: (TK # 2) 10,000 gallons
- (b) Type of tanks:
- (c) Product stored in each tank: (TK # 2) Gasoline Contractor states a manway will be installed.
- (d) Reason for tanks being entered: Contractor states a manway will be installed.
- (e) Manway accessible at grade: Contractor states a manway will be installed.
- (4) The owner must notify this Office when completion of tank entry has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at <u>www.state.il.us/osfm</u> or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). Tank #2 began taking on water. Visual inspection shows water leaking into tank through seam in fiberglass tank. Containment Solutions has been hired to enter the tank and inspect it prior to making repairs.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Contact Person: Mark Romiti Phone:

Contractor Registration # Exp.

Sincerely,

Janu & Coffey

cc: Storage Tank Safety Specialist -Fire Department -Office Coordinator -Division File (Rev. - 1/98)