



Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, IL 62703  
2177851020

Revised

**FOR OFFICE USE ONLY**

Facility # 2010011  
Permit # 00350-2022UPG  
Request Rec'd 04/04/2022  
Amended Date 04/12/2022 DS  
Approval Date 4/4/2022 DS  
Permit Expires 10/4/2022

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

<b>(1) OWNER OF TANKS</b> - Corporation, partnership, or other business entity:  2441 Franklin, LLC 1983 Route 52 Hopewell Junction, NY 12533  Contact: Patty Garcia (845) 765-8507	<b>(2) FACILITY</b> - name and address where tanks are located:  2441 Franklin, LLC 2441 North Mannheim Road Franklin Park, IL 60131  Contact: Syed Kirmani (845) 765-8507
---	--

**(3) UPGRADE OR REPAIR OF TANKS:**

- (a) *Number and size of tanks being upgraded or repaired: (TK # 6) - 15,000*
- (b) *Type of tanks:*
- (c) *Type of piping: (TK # 6) Piping - Fiberglass Double Wall Ameron Dualoy 3000/L , (TK # 6) Piping - Shear Valves , (TK # 6) Piping - Flex Connector Steel*
- (d) *Product to be stored in each tank: (TK # 6) - Diesel Fuel*
- (e) *Type of leak detection being used:*
  - Tank:*
  - Piping: (TK # 6) Leak Detect - Piping - Non-Discriminating Sump Sensor with positive shutdown*
- (f) *Corrosion Protection being used:*
  - Tank:*
  - Piping:*
- (g) *Spill containment devices, piping, and dispenser containment devices:*
- (h) *Overfill prevention devices:*
- (i) *Manway accessible at grade:*

- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.

**(5) SPECIAL CONTINGENCIES :**

The diesel line between master dispenser #13 and it's satellite position has failed. The pipe is double walled so the leak cannot be isolated. The full 13' run will be replaced with fiberglass 3" over 2" pipe, and a new flex connector with shear valve.

Amendment Reason: The check box of the replaced line over 20 lf. was check by mistake. Only 13" of the Diesel line was replaced and it is less than 50%of the full run of the Diesel line.

Amendment Reason: The check box of the replaced line over 20 lf. was check by mistake. Only 13" of the Diesel line was replaced and it is less than 50%of the full run of the Diesel line.


Revision Reason: Added sensors

**(6) PERSON, FIRM OR COMPANY PERFORMING WORK:**

B & K Equipment Company  
2939 175th Street  
Lansing, IL 60438

Contact Person: Ed Angell  
Phone: (708) 474-3344  
Contractor Registration # IL1207 Exp. 2/14/2024

Sincerely,

A handwritten signature in cursive script, reading "Daniel G. Starks", is written over a horizontal line.

Daniel Starks

cc: Storage Tank Safety Specialist  
Division File