

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 7006062 Permit # 00676-2022LIN Request Rec'd 06/23/2022 Amended Date Approval Date 6/24/2022 SB Permit Expires 12/27/2022

Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Parts 174, 175 and 176. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, at which time the UST activity shall be scheduled. **THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Sesser, IL 62884

Yongxin Enterprises Inc. 201 N. Park St.

Contact: Lekhraj Ahuja (703) 350-1268

(2) **FACILITY** - name and address where tanks are located:

Midtown Package Liquors 201 N. Park Street Sesser, IL 62884

Contact: Tina Logsdon (618) 200-0214

(3) INSPECTION OF INTERIOR LINING OF TANKS:

- (a) Number and size of tanks being inspected: (TK # 2) 10,000, (TK # 3) 8,000
- (b) Type of tank(s):
- (c) Product stored in each tank: (TK # 2) Gasoline Regular, (TK # 3) Diesel Fuel
- (d) Manway accessible at grade: (TK # 2) Existing, (TK # 3) Existing
- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.sfm.illinois.govor by calling (217)785-1020.
- (6) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by section 175.500. Perform past due internal lining inspection

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Bolin Enterprises, Inc. 506 North East 15th Street PO Box 70

Casey, IL 62420

Contact Person: Scott Justice Phone: (217) 932-4533

Contractor Registration # IL002333 Exp. 10/10/2022

Sincerely,

Shelly Bradley

Shelly Bradley

cc: Storage Tank Safety Specialist Division File