

Fiber Glass Systems | NOV

February 10, 2025

Joseph Smolar
BP Products North America
30 S. Wacker Drive
Chicago, IL 60606

Dear Sir,


NOV Fiber Glass Systems (FGS) arrived at 1 Burwell Drive, Lincoln, IL 62656. Entered and visually inspect one 8' diameter 12,000 gallon double wall tank with no reported issues. Tank reported to be installed in 1997.

The techs entered the tank through an existing 22" manway and performed a visual inspection of the interior of the tank. There was no visual damage to report to the tank primary. Vertical and horizontal deflection measurements were taken. All measurements taken were within allowable deflection. Bottom flatness measurements were taken and is in spec.

Tank is approved to store biodiesel B-99.

Please retain a copy of this letter, along with your other tank records for future reference.

Your use of NOV FGS Field Services is appreciated. If you have any further questions, Please feel free to contact me at 1-800-822-1997 extension 1.


Respectfully yours,

Mr. Nicholas Hostetler
Field Service Supervisor

T +1 210.477.7500
nov.com/fgs

NOV Fiber Glass Systems
17115 San Pedro Avenue
Suite 200 San Antonio, Texas 78232